

viEGA



4 015211 628680



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

viEGA



4 015211 628703



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

12 x $\frac{3}{8}$

628 680

12 x $\frac{1}{2}$

628 703

viEGA



4 015211 628697



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

viEGA



4 015211 628710



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

15 x $\frac{1}{2}$

628 697

18 x $\frac{1}{2}$

628 710

viEGA



4 015211 628727



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

viEGA



4 015211 628734



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

18 x $\frac{3}{4}$

628 727

22 x $\frac{3}{4}$

628 734

viEGA



4 015211 628741



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

viEGA



4 015211 628758



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

22 x 1

628 741

28 x 1

628 758

viEGA



4 015211 628765



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

viEGA



4 015211 628772



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

28 x $1\frac{1}{4}$

628 765

35 x 1

628 772

viEGA



4 015211 627232



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

35 x 1¼

627 232

viEGA



4 015211 627249



**Profipress S-přechodový kus,
s SC-Contur, model 4511**

35 x 1½

627 249