

**viega**



4 015211 397036



**Profipress G-přechodový kus,  
s SC-Contur, model 2611.5**


d	G
15	1/2

**397 036**

**viega**



4 015211 382803



**Profipress G-přechodový kus,  
s SC-Contur, model 2611.5**

d	G
15	3/4

**382 803**

**viega**



4 015211 397043



**Profipress G-přechodový kus,  
s SC-Contur, model 2611.5**


d	G
18	1/2

**397 043**

**viega**



4 015211 382810



**Profipress G-přechodový kus,  
s SC-Contur, model 2611.5**

d	G
18	3/4

**382 810**

**viega**



4 015211 397050



**Profipress G-přechodový kus,  
s SC-Contur, model 2611.5**


d	G
22	1/2

**397 050**

**viega**



4 015211 382827



**Profipress G-přechodový kus,  
s SC-Contur, model 2611.5**

d	G
22	3/4

**382 827**