

viega



4 015211 648633

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



viega



4 015211 605254

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



d	Rp
12	3/8

648 633

d	Rp
12	1/2

605 254

viega



4 015211 642136

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



viega



4 015211 559557

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



d	Rp
15	3/8

642 136

d	Rp
15	1/2

559 557

viega



4 015211 642143

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



viega



4 015211 559090

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



d	Rp
15	3/4

642 143

d	Rp
18	1/2

559 090

viega



4 015211 559106

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



viega



4 015211 642150

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



d	Rp
18	3/4

559 106

VdS	d	Rp
✓	22	1/2

642 150

viega



4 015211 559113

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



viega



4 015211 642167

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



VdS	d	Rp
✓	22	3/4

559 113

VdS	d	Rp
✓	22	1

642 167

viega



4 015211 704759

**Prestabo-přechodový kus, s SC-Contur,
model 1112**



viega



4 015211 642181

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



28 x 1/2

704 759

VdS	d	Rp
✓	28	3/4

642 181

viega



4 015211 559120

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



viega



4 015211 642198

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



VdS	d	Rp
✓	28	1

559 120

VdS	d	Rp
✓	35	¾

642 198

viega



4 015211 704766

**Prestabo-přechodový kus, s SC-Contur,
model 1112**



viega



4 015211 642204

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



35 x 1

704 766

VdS	d	Rp
✓	35	1¼

642 204

viega



4 015211 704773

**Prestabo-přechodový kus, s SC-Contur,
model 1112**



viega



4 015211 642211

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



42 x 1¼

704 773

VdS	d	Rp
✓	42	1½

642 211

viega



4 015211 642228

**Prestabo-přechodový kus,
s SC-Contur, model 1112**



VdS	d	Rp
✓	54	2

642 228