

viEGA



4 015211 628857



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

viEGA



4 015211 628864



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

12 x $\frac{3}{8}$

628 857

15 x $\frac{1}{2}$

628 864

viEGA



4 015211 628871



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

viEGA



4 015211 628888



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

18 x $\frac{1}{2}$

628 871

18 x $\frac{3}{4}$

628 888

viEGA



4 015211 628895



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

viEGA



4 015211 628901



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

22 x $\frac{3}{4}$

628 895

22 x 1

628 901

viEGA



4 015211 628918



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

viEGA



4 015211 628925



**Profipress S-přechodový kus,
s SC-Contur, model 4512**

28 x 1

628 918

35 x $1\frac{1}{4}$

628 925