



**viega**


**Prestabo XL-přechodový kus, s SC-Contur, model 1112XL**

VdS	d	Rp
✓	64,0	2

**630 003****viega**


**Prestabo XL-přechodový kus, s SC-Contur, model 1112XL**

VdS	d	Rp
✓	64,0	2½

**630 010****viega**


**Prestabo XL-přechodový kus, s SC-Contur, model 1112XL**

VdS	d	Rp
✓	76,1	2½

**630 034****viega**

**Prestabo XL-přechodový kus, s SC-Contur, model 1112XL**

VdS	d	Rp
✓	88,9	3

**630 041****viega**

**Prestabo XL-přechodový kus, s SC-Contur, model 1112XL**

VdS	d	Rp
✓	108,0	4

**630 027**