

viEGA



4 015211 740177



**Megapress-přechodový kus
s SC-Contur, model 4211**

viEGA



4 015211 740160



**Megapress-přechodový kus
s SC-Contur, model 4211**

$\frac{3}{8}$ (17,2) x R $\frac{3}{8}$

740 177

$\frac{3}{8}$ (17,2) x R $\frac{1}{2}$

740 160

viEGA



4 015211 695279



**Megapress-přechodový kus
s SC-Contur, model 4211**

viEGA



4 015211 695286



**Megapress-přechodový kus
s SC-Contur, model 4211**

$\frac{1}{2}$ (21,3) x R $\frac{1}{2}$

695 279

$\frac{3}{4}$ (26,9) x R $\frac{3}{4}$

695 286

viEGA



4 015211 695293



**Megapress-přechodový kus
s SC-Contur, model 4211**

viEGA



4 015211 695309



**Megapress-přechodový kus
s SC-Contur, model 4211**

1 (33,7) x R 1

695 293


$1\frac{1}{4}$ (42,4) x R $1\frac{1}{4}$

695 309

viEGA



4 015211 695316



**Megapress-přechodový kus
s SC-Contur, model 4211**

viEGA



4 015211 695323



**Megapress-přechodový kus
s SC-Contur, model 4211**

$1\frac{1}{2}$ (48,3) x R $1\frac{1}{2}$

695 316

2 (60,3) x R 2

695 323