

viega

4 015211 740184




**Megapress-přechodový kus,
s SC-Contur, model 4212**

$\frac{3}{8}$ (17,2) x Rp $\frac{3}{8}$

740 184**viega**

4 015211 695330




**Megapress-přechodový
kus, s SC-Contur,
model 4212**

DN	D	Rp
15	$\frac{1}{2}$	$\frac{1}{2}$

695 330**viega**

4 015211 695354




**Megapress-přechodový
kus, s SC-Contur,
model 4212**

VdS	DN	D	Rp
✓	25	1	1

695 354**viega**

4 015211 695378



**Megapress-přechodový
kus, s SC-Contur,
model 4212**

VdS	DN	D	Rp
✓	40	$1\frac{1}{2}$	$1\frac{1}{2}$

695 378**viega**

4 015211 740191




**Megapress-přechodový kus,
s SC-Contur, model 4212**

$\frac{3}{8}$ (17,2) x Rp $\frac{1}{2}$

740 191**viega**

4 015211 695347




**Megapress-přechodový
kus, s SC-Contur,
model 4212**

VdS	DN	D	Rp
✓	20	$\frac{3}{4}$	$\frac{3}{4}$

695 347**viega**

4 015211 695361




**Megapress-přechodový
kus, s SC-Contur,
model 4212**

VdS	DN	D	Rp
✓	32	$1\frac{1}{4}$	$1\frac{1}{4}$

695 361**viega**

4 015211 695385



**Megapress-přechodový
kus, s SC-Contur,
model 4212**

VdS	DN	D	Rp
✓	50	2	2

695 385