

**viEGA**

4 015211 436575



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

d	Rp
15	½

**436 575****viEGA**

4 015211 436599



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

d	Rp
18	½

**436 599****viEGA**

4 015211 436612




**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	22	½

**436 612****viEGA**

4 015211 436636



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	22	1

**436 636****viEGA**

4 015211 436650



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	28	1

**436 650****viEGA**

4 015211 436582



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

d	Rp
15	¾

**436 582****viEGA**

4 015211 436605



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

d	Rp
18	¾

**436 605****viEGA**

4 015211 436629



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	22	¾

**436 629****viEGA**

4 015211 436643



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	28	¾

**436 643****viEGA**

4 015211 436667



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	35	¼

**436 667**

**viEGA**



4 015211 436674



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**


VdS	d	Rp
✓	42	1½

**436 674**

**viEGA**



4 015211 436681



**Sanpress Inox-  
přechodový kus,  
s SC-Contur, model 2312**

VdS	d	Rp
✓	54	2

**436 681**