

viEGA

4 015211 291075



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
12	3/8

291 075**viEGA**

4 015211 443726



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
14	1/2

443 726**viEGA**

4 015211 107543



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
15	1/2

107 543**viEGA**

4 015211 443733



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
16	1/2

443 733**viEGA**

4 015211 294519



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
18	3/4

294 519**viEGA**

4 015211 291068



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
12	1/2

291 068**viEGA**

4 015211 298074



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
15	3/8

298 074**viEGA**

4 015211 298098



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
15	3/4

298 098**viEGA**

4 015211 283483



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

d	Rp
18	1/2

283 483**viEGA**

4 015211 298067



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	22	1/2

298 067

viEGA

4 015211 108465



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	22	¾

108 465**viEGA**

4 015211 298128



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	22	1

298 128**viEGA**

4 015211 428174



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	28	½

428 174**viEGA**

4 015211 298081



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	28	¾

298 081**viEGA**

4 015211 114329



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	28	1

114 329**viEGA**

4 015211 298104



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	28	1¼

298 104**viEGA**

4 015211 357542



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	35	¾

357 542**viEGA**

4 015211 298111



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	35	1

298 111**viEGA**

4 015211 116774



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	35	1¼

116 774**viEGA**

4 015211 298050



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	42	1¼

298 050

viEGA



4 015211 124236



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	42	1½

124 236

viEGA



4 015211 365097



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	54	1½

365 097

viEGA



4 015211 195304



**Sanpress-přechodový
kus, s SC-Contur,
model 2212**

VdS	d	Rp
✓	54	2

195 304