

viEGA



4 015211 738891



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

viEGA



4 015211 738907



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

$\frac{1}{2}$ (21,3) x R $\frac{1}{2}$

738 891

$\frac{3}{4}$ (26,9) x Rp $\frac{1}{2}$

738 907

viEGA



4 015211 738914



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

viEGA



4 015211 738921



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

$\frac{3}{4}$ (26,9) x Rp $\frac{3}{4}$

738 914

1 (33,7) x Rp $\frac{3}{4}$

738 921

viEGA



4 015211 738938



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

viEGA



4 015211 738945



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

1 (33,7) x Rp 1

738 938

1 $\frac{1}{4}$ (42,4) x Rp 1 $\frac{1}{4}$

738 945

viEGA



4 015211 739058



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

viEGA



4 015211 739065



**Megapress G-přechodový
kus, s SC-Contur, model 4612**

1 $\frac{1}{2}$ (48,3) x Rp 1 $\frac{1}{2}$

739 058

2 (60,3) x Rp 2

739 065