

viEGA



4 015211 769574



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

viEGA



4 015211 769581



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

$\frac{3}{8}$ (17,2) x R $\frac{3}{8}$

769 574

$\frac{1}{2}$ (21,3) x R $\frac{1}{2}$

769 581

viEGA



4 015211 769598



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

viEGA



4 015211 769604



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

$\frac{3}{4}$ (26,9) x R $\frac{3}{4}$

769 598

1 (33,7) x R 1

769 604

viEGA



4 015211 769611



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

viEGA



4 015211 769628



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

$1\frac{1}{4}$ (42,4) x R $1\frac{1}{4}$

769 611

$1\frac{1}{2}$ (48,3) x R $1\frac{1}{2}$

769 628

viEGA



4 015211 769635



**Megapress S-přechodový
kus, s SC-Contur, model 4311**

2 (60,3) x R 2

769 635