

viEGA



4 015211 769642



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

viEGA



4 015211 769758



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

$\frac{3}{8}$ (17,2) x Rp $\frac{3}{8}$

769 642

$\frac{1}{2}$ (21,3) x R $\frac{1}{2}$

769 758

viEGA



4 015211 769765



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

viEGA



4 015211 769772



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

$\frac{3}{4}$ (26,9) x Rp $\frac{3}{4}$

769 765

1 (33,7) x Rp 1

769 772

viEGA



4 015211 769789



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

viEGA



4 015211 769796



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

$1\frac{1}{4}$ (42,4) x Rp $1\frac{1}{4}$

769 789

$1\frac{1}{2}$ (48,3) x Rp $1\frac{1}{2}$

769 796

viEGA



4 015211 769802



**Megapress S-přechodový
kus, s SC-Contur, model 4312**

2 (60,3) x Rp 2

769 802