

**viega**



4 015211 740207

**Megapress-přechodový kus,  
s SC-Contur, model 4213**



**viega**



4 015211 718787

**Megapress-přechodový kus,  
s SC-Contur, model 4213**



$\frac{3}{8}$  (17,2) x 15

**viega**



4 015211 767600

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**740 207**

DN	D	d
15	$\frac{1}{2}$	15



**viega**



4 015211 734121

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**718 787**



$\frac{1}{2}$  (21,3) x 18

**viega**



4 015211 718794

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**767 600**

DN	D	d
20	$\frac{3}{4}$	15



**viega**



4 015211 734138

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**734 121**



$\frac{3}{4}$  (26,9) x 22

**viega**



4 015211 718800

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**718 794**

DN	D	d
25	1	15



**viega**



4 015211 718817

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**734 138**



1 (33,7) x 28

**viega**



4 015211 718824

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**718 800**

$1\frac{1}{4}$  (42,4) x 35

**viega**



4 015211 718831

**Megapress-přechodový kus,  
s SC-Contur, model 4213**

**718 817**



$1\frac{1}{2}$  (48,3) x 42

**718 824**

2 (60,3) x 54

**718 831**