

**viega**



4 015211 629137

**Profipress S-přechodový kus,  
s SC-Contur, model 4511.4**




**viega**



4 015211 629144

**Profipress S-přechodový kus,  
s SC-Contur, model 4511.4**



d	G
18	3/4

**629 137**

d	G
22	1

**629 144**