

viega



4 015211 628857

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



viega



4 015211 628864

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



d	Rp
12	3/8

628 857

d	Rp
15	1/2

628 864

viega



4 015211 628871

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



viega



4 015211 628888

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



d	Rp
18	1/2

628 871

d	Rp
18	3/4

628 888

viega



4 015211 628895

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



viega



4 015211 628901

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



d	Rp
22	3/4

628 895

d	Rp
22	1

628 901

viega



4 015211 628918

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



viega



4 015211 628925

**Profipress S-přechodový kus,
s SC-Contur, model 4512**



d	Rp
28	1

628 918

d	Rp
35	1 1/4

628 925