


**viega**



4 015211 629953

**Prestabo XL-přechodový kus,  
s SC-Contur, model 1111XL**




**viega**



4 015211 629960

**Prestabo XL-přechodový kus,  
s SC-Contur, model 1111XL**



| VdS | d    | R |
|-----|------|---|
| ✓   | 64,0 | 2 |

**629 953**

| VdS | d    | R  |
|-----|------|----|
| ✓   | 64,0 | 2½ |


**629 960**

**viega**



4 015211 629977

**Prestabo XL-přechodový kus,  
s SC-Contur, model 1111XL**




**viega**



4 015211 629984

**Prestabo XL-přechodový kus,  
s SC-Contur, model 1111XL**



| VdS | d    | R  |
|-----|------|----|
| ✓   | 76,1 | 2½ |

**629 977**

| VdS | d    | R |
|-----|------|---|
| ✓   | 88,9 | 3 |


**629 984**

**viega**



4 015211 629991

**Prestabo XL-přechodový kus,  
s SC-Contur, model 1111XL**



**629 991**

| VdS | d     | R |
|-----|-------|---|
| ✓   | 108,0 | 4 |