


viega



4 015211 630003

**Prestabo XL-přechodový kus,
s SC-Contur, model 112XL**




viega



4 015211 630010

**Prestabo XL-přechodový kus,
s SC-Contur, model 112XL**



| VdS | d | Rp |
|-----|------|----|
| ✓ | 64,0 | 2 |

630 003

| VdS | d | Rp |
|-----|------|----|
| ✓ | 64,0 | 2½ |


630 010

viega



4 015211 630034

**Prestabo XL-přechodový kus,
s SC-Contur, model 112XL**




viega



4 015211 630041

**Prestabo XL-přechodový kus,
s SC-Contur, model 112XL**



| VdS | d | Rp |
|-----|------|----|
| ✓ | 76,1 | 2½ |

630 034

| VdS | d | Rp |
|-----|------|----|
| ✓ | 88,9 | 3 |


630 041

viega



4 015211 630027

**Prestabo XL-přechodový kus,
s SC-Contur, model 112XL**



630 027

| VdS | d | Rp |
|-----|-------|----|
| ✓ | 108,0 | 4 |