

viega

4 015211 641849



**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

d	Rp
15	1/2

641 849**viega**

4 015211 643461

**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

VdS	d	Rp
✓	22	3/4

643 461**viega**

4 015211 643485

**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

VdS	d	Rp
✓	28	1

643 485**viega**

4 015211 643508

**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

VdS	d	Rp
✓	42	1 1/2

643 508**viega**

4 015211 643454



**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

d	Rp
18	1/2

643 454**viega**

4 015211 643478

**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

VdS	d	Rp
✓	22	1

643 478**viega**

4 015211 643492

**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

VdS	d	Rp
✓	35	1 1/4

643 492**viega**

4 015211 643515

**Prestabo-přechodové šroubení,
s SC-Contur, model 1162**

VdS	d	Rp
✓	54	2

643 515