

viega



4 015211 740177



**Megapress-přechodový kus,
s SC-Contur, model 4211**


$\frac{3}{8}$ (17,2) x R $\frac{3}{8}$

740 177

viega



4 015211 695279



**Megapress-přechodový kus,
s SC-Contur, model 4211**


DN	D	R
15	$\frac{1}{2}$	$\frac{1}{2}$

695 279

viega



4 015211 695286



**Megapress-přechodový kus,
s SC-Contur, model 4211**


VdS	DN	D	R
✓	25	1	1

695 293

viega



4 015211 695316



**Megapress-přechodový kus,
s SC-Contur, model 4211**


VdS	DN	D	R
✓	40	$1\frac{1}{2}$	$1\frac{1}{2}$

695 316

viega



4 015211 740160



**Megapress-přechodový kus,
s SC-Contur, model 4211**


$\frac{3}{8}$ (17,2) x R $\frac{1}{2}$

740 160

viega



4 015211 695286



**Megapress-přechodový kus,
s SC-Contur, model 4211**


VdS	DN	D	R
✓	20	$\frac{3}{4}$	$\frac{3}{4}$

695 279

viega



4 015211 695309



**Megapress-přechodový kus,
s SC-Contur, model 4211**


VdS	DN	D	R
✓	32	$1\frac{1}{4}$	$1\frac{1}{4}$

695 293

viega



4 015211 695323



**Megapress-přechodový kus,
s SC-Contur, model 4211**

VdS	DN	D	R
✓	50	2	2

695 316

695 323