

viega



4 015211 740184

**Megapress-přechodový kus,
s SC-Contur, model 4212**

$\frac{3}{8}$ (17,2) x Rp $\frac{3}{8}$

viega



4 015211 695330

**Megapress-přechodový kus,
s SC-Contur, model 4212**

DN	D	Rp
15	$\frac{1}{2}$	$\frac{1}{2}$

viega



4 015211 695354

**Megapress-přechodový kus,
s SC-Contur, model 4212**

VdS	DN	D	Rp
✓	25	1	1

viega



4 015211 695378

**Megapress-přechodový kus,
s SC-Contur, model 4212**

VdS	DN	D	Rp
✓	40	$1\frac{1}{2}$	$1\frac{1}{2}$



740 184



695 330



695 354



695 378

viega



4 015211 740191

**Megapress-přechodový kus,
s SC-Contur, model 4212**

$\frac{3}{8}$ (17,2) x Rp $\frac{1}{2}$

viega



4 015211 695347

**Megapress-přechodový kus,
s SC-Contur, model 4212**

VdS	DN	D	Rp
✓	20	$\frac{3}{4}$	$\frac{3}{4}$

viega



4 015211 695361

**Megapress-přechodový kus,
s SC-Contur, model 4212**

VdS	DN	D	Rp
✓	32	$1\frac{1}{4}$	$1\frac{1}{4}$

viega



4 015211 695385

**Megapress-přechodový kus,
s SC-Contur, model 4212**

VdS	DN	D	Rp
✓	50	2	2



740 191



695 347



695 361



695 385