

viega



4 015211 436575



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

d	Rp
15	1/2

436 575

viega



4 015211 436582



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

d	Rp
15	3/4

436 582

viega



4 015211 436599



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

viega



4 015211 436605



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

d	Rp
18	1/2

436 599

d	Rp
18	3/4

436 605

viega



4 015211 436612



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

viega



4 015211 436629



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

VdS	d	Rp
✓	22	1/2

436 612

VdS	d	Rp
✓	22	3/4

436 629

viega



4 015211 436636



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

viega



4 015211 436643



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

VdS	d	Rp
✓	22	1

436 636

VdS	d	Rp
✓	28	3/4

436 643

viega



4 015211 436650



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

viega



4 015211 436667



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

VdS	d	Rp
✓	28	1

436 650

VdS	d	Rp
✓	35	1 1/4

436 667

viega



4 015211 436674



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

viega



4 015211 436681



**Sanpress Inox-přechodový kus,
s SC-Contur, model 2312**

VdS	d	Rp
✓	42	1 1/2

436 674

VdS	d	Rp
✓	54	2

436 681