

viega



4 015211 486839



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
15	1/2

486 839

viega



4 015211 486846



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
15	3/4

486 846

viega



4 015211 486853



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
18	1/2

486 853

viega



4 015211 486860



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
18	3/4

486 860

viega



4 015211 486877



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
22	1/2

486 877

viega



4 015211 486884



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
22	3/4

486 884

viega



4 015211 486891



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
28	1

486 891

viega



4 015211 486907



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
28	3/4

486 907

viega



4 015211 486914



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
28	1

486 914

viega



4 015211 486921



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
35	1 1/4

486 921

viega



4 015211 486938



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
42	1 1/2

486 938

viega



4 015211 486945



**Sanpress Inox G-přechodový kus,
s SC-Contur, model 0212**

d	Rp
54	2

486 945