

viega

4 015211 292980

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**292 980**

d	Rp
12	1/2

viega

4 015211 125660

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**125 660**

d	Rp
15	1/2

viega

4 015211 283469

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**283 469**

d	Rp
18	1/2

viega

4 015211 283452

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**283 452**

d	Rp
18	3/4

viega

4 015211 122614

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**122 614**

d	Rp
22	3/4

viega

4 015211 132637

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**132 637**

d	Rp
22	1

viega

4 015211 128159

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**128 159**

d	Rp
28	1

viega

4 015211 132729

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**132 729**

d	Rp
35	1 1/4

viega

4 015211 139872

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**139 872**

d	Rp
42	1 1/2

viega

4 015211 221676

**Sanpress-přechodové
šroubení 90°, s SC-Contur,
model 2255**

**221 676**

d	Rp
54	2