


viega



4 015211 739423

Megapress-T-kus, s SC-Contur, model 4218




739 423

viega



4 015211 694968

Megapress-T-kus, s SC-Contur, model 4218



694 968


3/8 (17,2)

viega



4 015211 695026

Megapress-T-kus, s SC-Contur, model 4218




695 026

viega



4 015211 694975

Megapress-T-kus, s SC-Contur, model 4218



694 975

DN	D1	D2	D3
20	3/4	1/2	3/4


VdS	DN	D1	D2	D3
✓	20	3/4	3/4	3/4

viega



4 015211 695033

Megapress-T-kus, s SC-Contur, model 4218




695 033

viega



4 015211 695040

Megapress-T-kus, s SC-Contur, model 4218



695 040

DN	D1	D2	D3
25	1	1/2	1


VdS	DN	D1	D2	D3
✓	25	1	3/4	1

viega



4 015211 699024

Megapress-T-kus, s SC-Contur, model 4218




699 024

viega



4 015211 747794

Megapress-T-kus, s SC-Contur, model 4218



747 794

VdS	DN	D1	D2	D3
✓	25	1	1	1


DN	D1	D2	D3
32	1 1/4	1/2	1 1/4

viega



4 015211 695057

Megapress-T-kus, s SC-Contur, model 4218




695 057

viega



4 015211 695095

Megapress-T-kus, s SC-Contur, model 4218



695 095

VdS	DN	D1	D2	D3
✓	32	1 1/4	3/4	1 1/4


VdS	DN	D1	D2	D3
✓	32	1 1/4	1	1 1/4

viega



4 015211 694999

Megapress-T-kus, s SC-Contur, model 4218




694 999

viega



4 015211 695064

Megapress-T-kus, s SC-Contur, model 4218



695 064

VdS	DN	D1	D2	D3
✓	32	1 1/4	1 1/4	1 1/4


DN	D1	D2	D3
40	1 1/2	1/2	1 1/2

viega



4 015211 695071

Megapress-T-kus, s SC-Contur, model 4218



695 071


VdS	DN	D1	D2	D3
✓	40	1½	¾	1½

viega



4 015211 695101

Megapress-T-kus, s SC-Contur, model 4218



695 101


VdS	DN	D1	D2	D3
✓	40	1½	1	1½

viega



4 015211 695088

Megapress-T-kus, s SC-Contur, model 4218



695 088


VdS	DN	D1	D2	D3
✓	40	1½	1¼	1½

viega



4 015211 695002

Megapress-T-kus, s SC-Contur, model 4218



695 002


VdS	DN	D1	D2	D3
✓	40	1½	1½	1½

viega



4 015211 695118

Megapress-T-kus, s SC-Contur, model 4218



695 118


DN	D1	D2	D3
50	2	½	2

viega



4 015211 695125

Megapress-T-kus, s SC-Contur, model 4218



695 125


VdS	DN	D1	D2	D3
✓	50	2	¾	2

viega



4 015211 695132

Megapress-T-kus, s SC-Contur, model 4218



695 132


VdS	DN	D1	D2	D3
✓	50	2	1	2

viega



4 015211 695149

Megapress-T-kus, s SC-Contur, model 4218



695 149


VdS	DN	D1	D2	D3
✓	50	2	1¼	2

viega



4 015211 695156

Megapress-T-kus, s SC-Contur, model 4218



695 156


VdS	DN	D1	D2	D3
✓	50	2	1½	2

viega



4 015211 695019

Megapress-T-kus, s SC-Contur, model 4218



695 019

VdS	DN	D1	D2	D3
✓	50	2	2	2