


viega



4 015211 770952




**Megapress S-přechodové šroubení,
s SC-Contur, model 4365**

$\frac{1}{2}$ (21,3) x R $\frac{1}{2}$

viega



4 015211 770976




**Megapress S-přechodové šroubení,
s SC-Contur, model 4365**

1 (33,7) x R 1

viega



4 015211 770990




**Megapress S-přechodové šroubení,
s SC-Contur, model 4365**

$1\frac{1}{2}$ (48,3) x R $1\frac{1}{2}$

viega



4 015211 770969



**Megapress S-přechodové šroubení,
s SC-Contur, model 4365**

$\frac{3}{4}$ (26,9) x R $\frac{3}{4}$

viega



4 015211 770983




**Megapress S-přechodové šroubení,
s SC-Contur, model 4365**

$1\frac{1}{4}$ (42,4) x R $1\frac{1}{4}$

viega



4 015211 771003



**Megapress S-přechodové šroubení,
s SC-Contur, model 4365**

2 (60,3) x R 2

770 952

770 969

770 976

770 983

770 990

771 003