


**viega**



4 015211 770952




**Megapress S adapter union  
with SC-Contur, Model 4365**

**viega**



4 015211 770969



**Megapress S adapter union  
with SC-Contur, Model 4365**


$\frac{1}{2}$  (21,3) x R  $\frac{1}{2}$

**770 952**

**viega**



4 015211 770976



**Megapress S adapter union  
with SC-Contur, Model 4365**


$\frac{3}{4}$  (26,9) x R  $\frac{3}{4}$

**770 969**

**viega**



4 015211 770983



**Megapress S adapter union  
with SC-Contur, Model 4365**


1 (33,7) x R 1

**770 976**

**viega**



4 015211 770990



**Megapress S adapter union  
with SC-Contur, Model 4365**

1  $\frac{1}{4}$  (42,4) x R 1  $\frac{1}{4}$

**770 983**

**viega**



4 015211 771003



**Megapress S adapter union  
with SC-Contur, Model 4365**

1  $\frac{1}{2}$  (48,3) x R 1  $\frac{1}{2}$

**770 990**

2 (60,3) x R 2

**771 003**