


viega



4 015211 770952

**Megapress S adapter union,
with SC-Contur, Model 4365**




viega




4 015211 770969

**Megapress S adapter union,
with SC-Contur, Model 4365**



DN	D	R
15	1/2	1/2


770 952



VdS	DN	D	R
✓	20	3/4	3/4

**Megapress S adapter union,
with SC-Contur, Model 4365**

770 969



viega



4 015211 770976

**Megapress S adapter union,
with SC-Contur, Model 4365**

viega




4 015211 770983

**Megapress S adapter union,
with SC-Contur, Model 4365**

VdS	DN	D	R
✓	25	1	1

770 976



VdS	DN	D	R
✓	32	1 1/4	1 1/4

**Megapress S adapter union,
with SC-Contur, Model 4365**

770 983



viega



4 015211 770990

**Megapress S adapter union
with SC-Contur, Model 4365**

viega



4 015211 771003

**Megapress S adapter union
with SC-Contur, Model 4365**

1 1/2 (48,3) x R 1 1/2

770 990

2 (60,3) x R 2

771 003