

**viega**



4 015211 441104

Supistusyhde, malli 3241



**viega**



4 015211 441111

Supistusyhde, malli 3241



$\frac{1}{4} \times \frac{1}{8}$

**viega**



4 015211 281823

Supistusyhde, malli 3241

**441 104**



$\frac{3}{8} \times \frac{1}{8}$

**viega**



4 015211 441098

Supistusyhde, malli 3241

**441 111**



$\frac{3}{8} \times \frac{1}{4}$

**viega**



4 015211 319076

Supistusyhde, malli 3241

**281 823**



$\frac{1}{2} \times \frac{1}{8}$

**viega**



4 015211 266516

Supistusyhde, malli 3241

**441 098**



$\frac{1}{2} \times \frac{1}{4}$

**viega**



4 015211 320409

Supistusyhde, malli 3241

**319 076**



$\frac{1}{2} \times \frac{3}{8}$

**viega**



4 015211 266509

Supistusyhde, malli 3241

**266 516**



$\frac{3}{4} \times \frac{1}{4}$

**viega**



4 015211 266493

Supistusyhde, malli 3241

**320 409**



$\frac{3}{4} \times \frac{3}{8}$

**viega**



4 015211 266455

Supistusyhde, malli 3241

**266 509**



$\frac{3}{4} \times \frac{1}{2}$

**viega**



4 015211 266486

Supistusyhde, malli 3241

**266 493**



$1 \times \frac{3}{8}$

**viega**



4 015211 266479

Supistusyhde, malli 3241

**266 455**



$1 \times \frac{1}{2}$

**266 486**

$1 \times \frac{3}{4}$

**266 479**

**viega**



Supistusyhde, malli 3241



**viega**



Supistusyhde, malli 3241



1 1/4 x 1/2

**viega**



Supistusyhde, malli 3241



**267 582**

1 1/4 x 3/4

**viega**



Supistusyhde, malli 3241

**267 568**



1 1/4 x 1

**viega**



Supistusyhde, malli 3241



**266 462**

1 1/2 x 1/2

**viega**



Supistusyhde, malli 3241

**267 742**



1 1/2 x 3/4

**viega**



Supistusyhde, malli 3241



**267 728**

1 1/2 x 1

**viega**



Supistusyhde, malli 3241

**267 605**



1 1/2 x 1 1/4

**viega**



Supistusyhde, malli 3241



**267 704**

2 x 1/2

**viega**



Supistusyhde, malli 3241

**317 089**



2 x 3/4

**viega**



Supistusyhde, malli 3241



**267 681**

2 x 1

**viega**



Supistusyhde, malli 3241

**267 667**



2 x 1 1/4

**267 643**

2 x 1 1/2

**267 629**

**viega**



4 015211 321772

**Supistusyhde, malli 3241**



**viega**



4 015211 321765

**Supistusyhde, malli 3241**



2½ x 1

**viega**



4 015211 321864

**Supistus, malli 3241**

**321 772**



2½ x 1¼

**viega**



4 015211 322533

**Supistus, malli 3241**

**321 765**



2½ x 1½

**viega**



4 015211 321840

**Supistus, malli 3241**

**321 864**



2½ x 2

**viega**



4 015211 321857

**Supistus, malli 3241**

**322 533**



3 x 1½

**viega**



4 015211 321871

**Supistus, malli 3241**

**321 840**



3 x 2

**viega**



4 015211 321888

**Supistus, malli 3241**

**321 857**



3 x 2½

**321 871**

4 x 3

**321 888**