

viEGA

4 015211 346935

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
12	3/8

346 935**viEGA**

4 015211 346942

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
12	1/2

346 942**viEGA**

4 015211 345822

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
15	1/2

345 822**viEGA**

4 015211 345839

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
15	3/4

345 839**viEGA**

4 015211 345846

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
18	1/2

345 846**viEGA**

4 015211 345853

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
18	3/4

345 853**viEGA**

4 015211 345860

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
22	1/2

345 860**viEGA**

4 015211 345877

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
22	3/4

345 877**viEGA**

4 015211 345884

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
22	1

345 884**viEGA**

4 015211 345891

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
28	1

345 891

viega



4 015211 345907

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
35	1¼

345 907

viega



4 015211 345914

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
42	1½

345 914

viega



4 015211 345921

Coude de transition 90° Profipress G, avec SC-Contur, FF, modèle 2614.2



d	Rp
54	2

345 921