

**viega**



4 015211 346935

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**346 935**

d	Rp
12	3/8

**viega**



4 015211 346942

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**346 942**

d	Rp
12	1/2

**viega**



4 015211 345822

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 822**

d	Rp
15	1/2

**viega**



4 015211 345839

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 839**

d	Rp
15	3/4

**viega**



4 015211 345846

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 846**

d	Rp
18	1/2

**viega**



4 015211 345853

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 853**

d	Rp
18	3/4

**viega**



4 015211 345860

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 860**

d	Rp
22	1/2

**viega**



4 015211 345877

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 877**

d	Rp
22	3/4

**viega**



4 015211 345884

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 884**

d	Rp
22	1

**viega**



4 015211 345891

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 891**

d	Rp
28	1

**viega**



4 015211 345907

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 907**

d	Rp
35	1 1/4

**viega**



4 015211 345914

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



**345 914**

d	Rp
42	1 1/2

**viega**



4 015211 345921

**Coude de transition 90°  
Profipress G, avec SC-Contur, FF,  
modèle 2614.2**



d	Rp
54	2

**345 921**