


viega

4 015211 705596

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**


d1	G	d2
15	$\frac{1}{4}$	15

**705 596****viega**

4 015211 705602

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**


d1	G	d2
18	$\frac{1}{4}$	18

**705 602****viega**

4 015211 705619

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**


d1	G	d2
22	$\frac{1}{4}$	22

**705 619****viega**

4 015211 705626

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**


d1	G	d2
28	$\frac{1}{4}$	28

**705 626****viega**

4 015211 705633

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**


d1	G	d2
35	$\frac{1}{4}$	35

**705 633****viega**

4 015211 705640

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**


d1	G	d2
42	$\frac{1}{4}$	42

**705 640****viega**

4 015211 705855

**Sanpress-T-kus, G $\frac{1}{4}$,
se zásuvným kon-
cem, s SC-Contur,
model 2217.4**

d1	G	d2
54	$\frac{1}{4}$	54

**705 855**