


viEGA



4 015211 577674



Profipress XL-přechodový kus, s SC-Contur, model 2411XL


d	R
64,0	2½

577 674

viEGA



4 015211 534141



Profipress XL-přechodový kus, s SC-Contur, model 2411XL


d	R
88,9	3

534 141

viEGA



4 015211 534134



Profipress XL-přechodový kus, s SC-Contur, model 2411XL


d	R
76,1	2½

534 134

viEGA



4 015211 534158



Profipress XL-přechodový kus, s SC-Contur, model 2411XL

d	R
108,0	4

534 158