


viEGA



4 015211 738730



**Megapress G-přechodový
kus, s SC-Contur, model 4611**

viEGA



4 015211 738747



**Megapress G-přechodový
kus, s SC-Contur, model 4611**

$\frac{1}{2}$ (21,3) x R $\frac{1}{2}$

738 730

$\frac{3}{4}$ (26,9) x R $\frac{3}{4}$

738 747

viEGA



4 015211 738853



**Megapress G-přechodový
kus, s SC-Contur, model 4611**

viEGA



4 015211 738860



**Megapress G-přechodový
kus, s SC-Contur, model 4611**

1 (33,7) x R 1

738 853

1 $\frac{1}{4}$ (42,4) x R 1 $\frac{1}{4}$

738 860

viEGA



4 015211 738877



**Megapress G-přechodový
kus, s SC-Contur, model 4611**

viEGA



4 015211 738884



**Megapress G-přechodový
kus, s SC-Contur, model 4611**

1 $\frac{1}{2}$ (48,3) x R 1 $\frac{1}{2}$

738 877

2 (60,3) x R 2

738 884