


viega

4 015211 793401




**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

DN1	vnější Ø	DN2	R
32	38	20	¾

793 401**viega**

4 015211 793418




**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

DN1	vnější Ø	DN2	R
32	38	32	1¼

793 418**viega**


4 015211 783112



**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

viega

4 015211 793395




**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

DN1	vnější Ø	DN2	R
32	38	25	1

793 395**viega**

4 015211 754860



**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

44,5 x R 1

754 860**viega**

4 015211 783129



**Megapress-přechodový kus,
s SC-Contur, model 4211.3**


44,5 x R 1 1/4

783 112

44,5 x R 1 1/2

783 129**viega**


4 015211 754877



**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

viega

4 015211 783136



**Megapress-přechodový kus,
s SC-Contur, model 4211.3**


57,0 x R 1 1/4

754 877

57,0 x R 1 1/2)

783 136**viega**

4 015211 783143



**Megapress-přechodový kus,
s SC-Contur, model 4211.3**

57,0 x R 2

783 143