


**viEGA**



4 015211 352707

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
15	½	15


**352 707**

**viEGA**



4 015211 352714

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
18	½	18


**352 714**

**viEGA**



4 015211 352721

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
22	½	22


**352 721**

**viEGA**



4 015211 352738

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
22	¾	22


**352 738**

**viEGA**



4 015211 352745

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
28	½	28


**352 745**

**viEGA**



4 015211 352752

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
28	¾	28


**352 752**

**viEGA**



4 015211 352769

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
35	½	35


**352 769**

**viEGA**



4 015211 361327

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
35	1	35


**361 327**

**viEGA**



4 015211 352776

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
42	½	42


**352 776**

**viEGA**



4 015211 361334

**Profipress G-T-kus, s SC-Contur, model 2617.2**



d1	Rp	d2
42	1	42


**361 334**

**viEGA**



4 015211 352783

**Profipress G-  
T-kus, s SC-Contur,  
model 2617.2**



**352 783**


d1	Rp	d2
54	1/2	54

**viEGA**



4 015211 361341

**Profipress G-  
T-kus, s SC-Contur,  
model 2617.2**



**361 341**

d1	Rp	d2
54	1	54