

**viEGA**



4 015211 346935

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



**viEGA**



4 015211 346942

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



12 x 3/8

**346 935**

12 x 1/2

**346 942**

**viEGA**



4 015211 345822

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



**viEGA**



4 015211 345839

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



15 x 1/2

**345 822**

15 x 3/4

**345 839**

**viEGA**



4 015211 345846

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



**viEGA**



4 015211 345853

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



18 x 1/2

**345 846**

18 x 3/4

**345 853**

**viEGA**



4 015211 345860

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



**viEGA**



4 015211 345877

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



22 x 1/2

**345 860**

22 x 3/4

**345 877**

**viEGA**



4 015211 345884

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



**viEGA**



4 015211 345891

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



22 x 1

**345 884**

28 x 1

**345 891**

**viEGA**



4 015211 345907

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



35 x 1¼

**345 907**

**viEGA**



4 015211 345914

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



54 x 2

**345 921**

**viEGA**



4 015211 345914

**Profipress G-přechodové  
koleno 90°  
s SC-Contur, model 2614.2**



42 x 1½

**345 914**