


**viega**



4 015211 605193

**Prestabo-T-kus, s SC-Contur, model 1118**




**viega**



4 015211 605216

**Prestabo-T-kus, s SC-Contur, model 1118**



d1	d2	d3
12	12	12

**605 193**

d1	d2	d3
12	15	12


**605 216**

**viega**



4 015211 605209

**Prestabo-T-kus, s SC-Contur, model 1118**




**viega**



4 015211 558611

**Prestabo-T-kus, s SC-Contur, model 1118**



d1	d2	d3
15	12	15

**605 209**

15


**558 611**

**viega**



4 015211 642549

**Prestabo-T-kus, s SC-Contur, model 1118**




**viega**



4 015211 558857

**Prestabo-T-kus, s SC-Contur, model 1118**



d1	d2	d3
15	18	15

**642 549**

15 x 22 x 15


**558 857**

**viega**



4 015211 648596

**Prestabo-T-kus, s SC-Contur, model 1118**




**viega**



4 015211 558680

**Prestabo-T-kus, s SC-Contur, model 1118**



d1	d2	d3
18	12	18

**648 596**

18 x 15 x 18


**558 680**

**viega**



4 015211 704681

**Prestabo-T-kus, s SC-Contur, model 1118**




**viega**



4 015211 558628

**Prestabo-T-kus, s SC-Contur, model 1118**



18 x 18 x 15

**704 681**

18


**558 628**

**viega**



4 015211 558864

**Prestabo-T-kus, s SC-Contur, model 1118**




**viega**



4 015211 648602

**Prestabo-T-kus, s SC-Contur, model 1118**



18 x 22 x 18

**558 864**

d1	d2	d3
22	12	22


**648 602**

**viega**



4 015211 642617

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**viega**



4 015211 558697

**Prestabo-T-kus, s SC-Contur,  
model 1118**



d1	d2	d3
22	15	15

**viega**




4 015211 642648

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**642 617**

22 x 15 x 22

**558 697**




**viega**



4 015211 558703

**Prestabo-T-kus, s SC-Contur,  
model 1118**



d1	d2	d3
22	18	18

**viega**




4 015211 642655

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**642 648**

22 x 18 x 22

**558 703**




**viega**



4 015211 558635

**Prestabo-T-kus, s SC-Contur,  
model 1118**



d1	d2	d3
22	22	15

**viega**




4 015211 558871

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**642 655**

22

**558 635**




**viega**



4 015211 558710

**Prestabo-T-kus, s SC-Contur,  
model 1118**



22 x 28 x 22

**viega**




4 015211 558727

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**558 871**

28 x 15 x 28

**558 710**




**viega**



4 015211 642693

**Prestabo-T-kus, s SC-Contur,  
model 1118**



28 x 18 x 28

**viega**




4 015211 558734

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**558 727**

VdS	d1	d2	d3
✓	28	22	22

**642 693**




**viega**



4 015211 558642

**Prestabo-T-kus, s SC-Contur,  
model 1118**



28 x 22 x 28

**558 734**

28


**558 642**

**viega**



4 015211 558741

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**558 741**

**viega**



4 015211 558758

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**558 758**


35 x 15 x 35

**viega**



4 015211 558765

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**558 765**

**viega**



4 015211 558772

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**558 772**

35 x 22 x 35

**viega**



4 015211 558659

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**558 659**

**viega**



4 015211 642556

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**642 556**


35

**viega**



4 015211 704698

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**704 698**

**viega**



4 015211 558789

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**558 789**

42 x 18 x 42

**viega**



4 015211 558796

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**558 796**

**viega**



4 015211 558802

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**558 802**

42 x 22 x 42

**viega**



4 015211 558666

**Prestabo-T-kus, s SC-Contur,  
model 1118**




**558 666**

**viega**



4 015211 642570

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**642 570**

42

d1	d2	d3
42	15	42

d1	d2	d3
54	15	54

**viega**



4 015211 723682

**Prestabo-T-kus, s SC-Contur,  
model 1118**



**viega**



4 015211 558819

**Prestabo-T-kus, s SC-Contur,  
model 1118**



d1	d2	d3
54	18	54

**viega**



4 015211 558826

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**723 682**

54 x 22 x 54

**558 819**




**viega**



4 015211 558833

**Prestabo-T-kus, s SC-Contur,  
model 1118**



54 x 28 x 54

**viega**



4 015211 558840

**Prestabo-T-kus, s SC-Contur,  
model 1118**

**558 826**

54 x 35 x 54

**558 833**




**viega**



4 015211 558673

**Prestabo-T-kus, s SC-Contur,  
model 1118**



54 x 42 x 54

**558 840**

54

**558 673**