

**viega**



4 015211 643546

**Prestabo-přírubový přechod,  
s SC-Contur, model 1159**

VdS	DN	d	po
✓	32	35	4


**viega**



4 015211 643560

**Prestabo-přírubový přechod,  
s SC-Contur, model 1159**

VdS	DN	d	po
✓	50	54	4



**643 546**


**viega**




4 015211 643553

**Prestabo-přírubový přechod,  
s SC-Contur, model 1159**

VdS	DN	d	po
✓	40	42	4



**643 553**



**643 560**