


**viega**



4 015211 619985

**Sanpress Inox XL-přechodový kus,  
s SC-Contur, model 2311XL**




**viega**



4 015211 482923

**Sanpress Inox XL-přechodový kus,  
s SC-Contur, model 2311XL**



d	R
64,0	2½

**619 985**

VdS	d	R
✓	76,1	2½


**482 923**

**viega**



4 015211 483128

**Sanpress Inox XL-přechodový kus,  
s SC-Contur, model 2311XL**




**viega**



4 015211 482930

**Sanpress Inox XL-přechodový kus,  
s SC-Contur, model 2311XL**



VdS	d	R
✓	88,9	3

**483 128**

VdS	d	R
✓	108,0	4

**482 930**