


viega



4 015211 577674

**Profipress XL-přechodový kus,
s SC-Contur, model 2411XL**




viega



4 015211 534134

**Profipress XL-přechodový kus,
s SC-Contur, model 2411XL**



d	R
64,0	2½

577 674

d	R
76,1	2½


534 134

viega



4 015211 534141

**Profipress XL-přechodový kus,
s SC-Contur, model 2411XL**




viega



4 015211 534158

**Profipress XL-přechodový kus,
s SC-Contur, model 2411XL**



d	R
88,9	3

534 141

d	R
108,0	4

534 158