

viega



4 015211 288068

**Sanpress-přechodový kus,
s SC-Contur, model 2213**



viega



4 015211 298876

**Sanpress-přechodový kus,
s SC-Contur, model 2213**



d1	d2
15	16

288 068

d1	d2
15	20

298 876