


**viega**



4 015211 736255

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**




**viega**



4 015211 754679

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**



DN	D	d
15	1/2	15

**736 255**

DN	D	d
15	1/2	18


**754 679**

**viega**



4 015211 736279

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**




**viega**



4 015211 736293

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**



DN	D	d
20	3/4	22

**736 279**

DN	D	d
25	1	28


**736 293**

**viega**



4 015211 736309

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**




**viega**



4 015211 736316

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**



DN	D	d
32	1 1/4	35

**736 309**

DN	D	d
40	1 1/2	42


**736 316**

**viega**



4 015211 736323

**Megapress-přechodový kus,  
s SC-Contur, model 4213.2**



**736 323**

DN	D	d
50	2	54