

viEGA



4 015211 346935



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

viEGA



4 015211 346942



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

12 x 3/8

346 935

12 x 1/2

346 942

viEGA



4 015211 345822



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

viEGA



4 015211 345839



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

15 x 1/2

345 822

15 x 3/4

345 839

viEGA



4 015211 345846



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

viEGA



4 015211 345853



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

18 x 1/2

345 846

18 x 3/4

345 853

viEGA



4 015211 345860



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

viEGA



4 015211 345877



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

22 x 1/2

345 860

22 x 3/4

345 877

viEGA



4 015211 345884



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

viEGA



4 015211 345891



**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**

22 x 1

345 884

28 x 1

345 891

viEGA



4 015211 345907

**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**



35 x 1¼

345 907

viEGA



4 015211 345914

**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**



54 x 2

345 921

viEGA



4 015211 345907

**Profipress G-
Übergangswinkel 90°
mit SC-Contur, Modell 2614.2**



42 x 1½

345 914