


**viEGA**



4 015211 605346




**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

**viEGA**



4 015211 648640



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

12 x 3/8

**605 346**

12 x 1/2

**648 640**

**viEGA**



4 015211 558406



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

**viEGA**



4 015211 558413



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

15 x 3/8

**558 406**


15 x 1/2

**558 413**

**viEGA**



4 015211 558420




**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

**viEGA**



4 015211 704643



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

18 x 1/2

**558 420**


22 x 1/2

**704 643**

**viEGA**



4 015211 558437



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

**viEGA**



4 015211 558444



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

22 x 3/4

**558 437**

28 x 1

**558 444**

**viEGA**



4 015211 558451



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

**viEGA**



4 015211 558468



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

35 x 1 1/4

**558 451**

42 x 1 1/2

**558 468**

**viEGA**



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114**

54 x 2

**558 475**