

**viega**



4 015211 605353



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

**viega**



4 015211 651398



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

12 x  $\frac{3}{8}$

**605 353**

**viega**



4 015211 601300



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

12 x  $\frac{1}{2}$

**651 398**

**viega**



4 015211 601317



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

15 x  $\frac{1}{2}$

**601 300**

**viega**



4 015211 704650



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

18 x  $\frac{1}{2}$

**601 317**

**viega**



4 015211 601324



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

22 x  $\frac{1}{2}$

**704 650**

**viega**



4 015211 601331



**Prestabo käyrä 90°**  
**SC-Contur, malli 1114.5**

22 x  $\frac{3}{4}$

**601 324**

28 x 1

**601 331**