

**viega**



4 015211 739379

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226



**viega**



4 015211 694579

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226



$\frac{3}{8}$  (17,2)

**viega**



4 015211 694586

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226

**739 379**



$\frac{1}{2}$  (21,3)

**viega**



4 015211 694593

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226

**694 579**



$\frac{3}{4}$  (26,9)

**viega**



4 015211 694609

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226

**694 586**



1 (33,7)

**viega**



4 015211 694616

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226

**694 593**



$1\frac{1}{4}$  (42,4)

**viega**



4 015211 694623

**Megapress käyrä 45°**

sis. SC-Contur, malli 4226

**694 609**



$1\frac{1}{2}$  (48,3)

**694 616**

2 (60,3)

**694 623**