

**viega**



4 015211 770341

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**viega**



4 015211 770655

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



$\frac{1}{2}$  (21,3) x  $\frac{3}{8}$  (17,2)

**viega**



4 015211 770662

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 341**

$\frac{3}{4}$  (26,9) x  $\frac{3}{8}$  (17,2)

**viega**



4 015211 770679

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 655**

$\frac{3}{4}$  (26,9) x  $\frac{1}{2}$  (21,3)

**viega**



4 015211 770686

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 662**

1 (33,7) x  $\frac{3}{8}$  (17,2)

**viega**



4 015211 770693

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 679**

1 (33,7) x  $\frac{1}{2}$  (21,3)

**viega**



4 015211 770709

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 686**

1 (33,7) x  $\frac{3}{4}$  (26,9)

**viega**



4 015211 799304

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 693**

$1\frac{1}{4}$  (42,4) x 1 (33,7)

**viega**



4 015211 770716

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 709**

VdS	dh	DN1	D1	DN2	D2
✓	✓	40	1½	25	1

**viega**



4 015211 799311

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**799 304**

$1\frac{1}{2}$  (48,3) x  $1\frac{1}{4}$  (42,4)

**viega**



4 015211 799328

**Megapress S supistusyhde**  
sis. SC-Contur, malli 4315.1



**770 716**

VdS	dh	DN1	D1	DN2	D2
✓	✓	50	2	25	1

**viega**



4 015211 770723

**Megapress S supistus**  
SC-Contur, malli 4315.1



**799 311**

VdS	dh	DN1	D1	DN2	D2
✓	✓	50	2	32	1¼

**799 328**

2 (60,3) x  $1\frac{1}{2}$  (48,3)

**770 723**