

viega



4 015211 346881

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



viega



4 015211 345532

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



d
12

346 881

d
15

345 532

viega



4 015211 345549

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



viega



4 015211 345556

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



d
18

345 549

d
22

345 556

viega



4 015211 345563

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



viega



4 015211 345570

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



d
28

345 563

d
35

345 570

viega



4 015211 345587

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



viega



4 015211 345594

**Coude 90° Profipress G, avec
SC-Contur, MF, modèle 2616.1**



d
42

345 587

d
54

345 594