


viega



4 015211 346911

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



viega



4 015211 346928

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



d	R
12	3/8

346 911

d	R
12	1/2


346 928

viega



4 015211 345747

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**




viega



4 015211 345754

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



d	R
15	1/2

345 747

d	R
18	1/2


345 754

viega



4 015211 345761

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



viega



4 015211 345778

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



d	R
18	3/4

345 761

d	R
22	3/4


345 778

viega



4 015211 345785

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



viega



4 015211 345792

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



d	R
28	1

345 785

d	R
35	1 1/4


345 792

viega



4 015211 345808

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**




viega



4 015211 345815

**Profipress G-Übergangsbocht 90°,
mit SC-Contur, MV, model 2614**



d	R
42	1 1/2

345 808

d	R
54	2

345 815