


**viega**



4 015211 122416

**Putkiliitin, malli 1832**




**viega**



4 015211 104498

**Putkiliitin, malli 1832**



$\frac{3}{8} \times \frac{1}{2}$

**122 416**

$\frac{1}{2} \times \frac{3}{4}$


**104 498**

**viega**



4 015211 108816

**Putkiliitin, malli 1832**




**viega**



4 015211 110734

**Putkiliitin, malli 1832**



$\frac{3}{4} \times 1$

**108 816**

$1 \times 1\frac{1}{4}$


**110 734**

**viega**



4 015211 119454

**Putkiliitin, malli 1832**




**viega**



4 015211 125219

**Putkiliitin, malli 1832**



$1\frac{1}{4} \times 1\frac{1}{2}$

**119 454**

$1\frac{1}{2} \times 1\frac{3}{4}$


**125 219**

**viega**



4 015211 131432

**Putkiliitin, malli 1832**



$2 \times 2\frac{3}{8}$

**131 432**